

FCP


Fritsch, Chiari & Partner ZT GmbH
www.fcp.at

FCP – Fritsch Chiari & Partner ZT GmbH
A-1140 Vienna, Diesterweggasse 3
Tel. +43 1 90 292, Fax +43 1 90 292-9000



Colle Isarco Viaduct – Structural assessment
based on periodic and permanent dynamic
monitoring

Dr. Andrea Mordini



Colle Isarco Viaduct:

- Located on the Brennero Highway in an alpine valley in the north of Italy.
- Two parallel equal structures.
- 13 spans for a total length of 1028 m.
- Main span 163 m with a suspended beam of 45 m.
- Post-tensioned reinforced concrete box girder.
- Fully isostatic structure.



I) Description of the work

II III IV



F C P

I) Description of the work

II III IV




F C P



F C P


The investigation at the Colle Isarco Viaduct included three essential parts:

- A detailed initial measurement campaign with BRIMOS® in March 2007.
- Two permanent monitoring systems – one for each carriageway, 2007-2008
- A second measurement campaign with BRIMOS® one year after the initial one in March 2008.




Sensor layout for the main structures

(the viaduct was loaded by traffic on one lane)



NORD



SUED

**Symbolskizze****Aufstellungsposition: linker Rand****F C P**







ANPSD (vertical direction) for all measurement files in the range 0-15 Hz.




Frequency trend in time




F C P


Eigenfrequency [Hz]	Measurement campaign 2007		
	carriageway North	carriageway South	
1 st bending mode	0.99	0.96	1BT main span
2 nd bending mode	1.10	1.10	1BT main cantilever
3 rd bending mode	3.83	3.89	1BT main hinged girder
4 th bending mode	6.11	6.10	2BT main cantilever




Mode shape 1 – 0.99 Hz 1BT main span








Mode shape 2 – 1.10 Hz 1BT main cantilever




Mode shape 3 – 3.83 Hz 1BT main hinged girder




Mode shape 4 – 6.11 Hz 2BT main cantilever



Vibration Intensity




Damping value distribution




Northern and Southern part of the bridge

Sensor layout for the northern part




Sensor layout for the southern part




Frequency trend in vertical direction, 0.2 – 25 Hz


CW North – Northern part




CW North – Southern part




CW South – Northern part



CW South – Southern part




Sensor layout for the main structures (the traffic was deviated)



Main structures

Structures' relevant stiffness-pattern in the vertical direction over the measurements' entire time period, for the reference sensor

CW North
Northern part




2BT main cantilever

1BT main hinged girder


1BT main canilever

1BT main span

CW North
Southern part



CW South
Northern part




2BT main cantilever

1BT main hinged girder

1BT main canilever

1BT main span



CW South
Southern part



Vibration Intensity Analysis - Main structures

CW North



Northern part



Southern part

CW South

Northern part



Southern part


F C P

Damping Analysis - Main structures

CW North

Northern part

1BT main span




Southern part

1BT main cantilever

CW South

Northern part

1BT main span




Southern part

1BT main cantilever

F C P


Northern and Southern part of the bridge



CW North - North	Deviation of the Eigenfrequencies 2007 vs. 2008 [%]
Joint 1-2	1.1
Joint 2 - 2.2	0.6
Joint 2.2-3.1	1.0
Joint 3.1-3.2	1.6
Joint 3.2 - 4.1	1.3
Joint 4.1-4.2	1.0
Joint 4.2 - 5.1	1.5
Joint 5.1-5.2	0.8
Joint 5.2 - 6.1	1.2
Joint 6.1-6.2	0.7
on average	1.1

CW South - North	Deviation of the Eigenfrequencies 2007 vs. 2008 [%]
Joint 1-2	1.4
Joint 2 - 2.2	1.2
Joint 2.2-3.1	0.9
Joint 3.1-3.2	1.8
Joint 3.2 - 4.1	0.9
Joint 4.1-4.2	1.5
Joint 4.2 - 5.1	1.2
Joint 5.1-5.2	1.6
Joint 5.2 - 6.1	0.6
Joint 6.1-6.2	0.9
on average	1.2

Eigenfrequencies deviation





CW North - South	Deviation of the Eigenfrequencies 2007 vs. 2008 [%]
Joint 10.1 - 10.2	1.4
Joint 10.2 - 11.1	1.0
Joint 11.1 - 11.2	1.8
Joint 11.2 - 12.1	1.6
Joint 12.1 - 13	0.9
Joint 13 - 14	1.7
on average	1.4

CW South - South	Deviation of the Eigenfrequencies 2007 vs. 2008 [%]
Joint 10.1 - 10.2	1.1
Joint 10.2 - 11.1	1.4
Joint 11.1 - 11.2	1.3
Joint 11.2 - 12.1	1.4
Joint 12.1 - 13	2.9
Joint 13 - 14	---
on average	1.6



Permanent Monitoring




Sensor layout



I II III IV) Progression of structural conditions 2007-2008





Frequency trend (0.2-50 Hz), spectra and temperature over the whole measurement period in the vertical direction (CW South)




Frequency trend, spectra and temperature sequence over the whole measurement period in vertical direction (CW South)

0.75 – 1.25 Hz
1BT main span
1BT main cantilever




5.5 – 6.5 Hz 2BT main cantilever




**Frequency trend, spectra and temperature sequence over one day
in vertical direction (CW South)**


0.75 – 1.25 Hz
1BT main span
1BT main cantilever




3.5 – 4.25 Hz
1BT main hinged girder



5.5 – 6.5 Hz
2BT main cantilever




Analysis of long-term torsion (environmental condition)



Trend of torsion – recorder (blue) and epi-sensor (red) –
versus trend of temperature (CW South)

- The structural dynamic response reveals the bridge to be in good conditions.
- Due to the design choices a high sensitivity to dynamic vibrations is present.
- The area of the main hinged girder and cantilevers will demand special attention.
 - In the trend cards of the CW South the eigenfrequencies of the main hinged girder show a wide variance.
 - Increased damping values are recorder. In 2007 in the CW South, in 2008 in the CW North.
- The vibration intensity analysis reveals values in the field II and III in the CW North and South respectively. Because of the fact that the traffic was restricted during the measurement this indicates a high dynamic sensitivity of the structure.
- These conditions could lead an accelerated decrease of the structural service life in the long term.
- To this respect, the static system without redundancy could be problematic.
- In these conditions, damages to load bearing parts can cause a sudden collapse of the system

According to BRIMOS® classification the structure is rated as category B:
„structures in good condition with local damages“.



- Immediate actions: NONE
 - Short-term actions: NONE
 - Mid-term actions: NONE
 - Long-term actions:
changes in
every six
- Permanent monitoring with real-time data analysis
and automatic alarming in the case of
the behaviour
- Monitoring of the overall structural condition by
periodic measurements with BRIMOS®
years.

This approach assures the determination of slowly progressing processes in the structure leading to the deterioration of the operational integrity.

Thanks for your kind attention